Stat.	
1.	This is 0.5 cm. Hole #7 — it is a drain pipe on S. edge of pit.
2	Elev of bottom of Hole
3	Elev at top of Hole
4	Elev at [illegible] of Hole
5	Dist [illegible] of Hole
6	Top [illegible] Hole
7.	Top of Hole
8	Top [illegible] Top of Hole
9	Top [illegible] " "
10	Top [illegible]

M. C. Rutile



M.C. Rutile July 1947

655 float qtz Brown Igneous Rock, float below O.A.

656 " " at Corner. Brown Rock well weathered. float to E and N

657 float qtz. float to E

658 " " in angle

659 " "

660 " " at corner.

661 E and Brown See Sketch

662 float qtz cut Sericite and Quartz between

663 " " Sericite

664 " " Quartz between, float N.

665 " " at Sharp Quartz

666 Corner of Boundary See Sketch

667 float qtz cut, Sericite to W., S.E. to edge of Igneous.

668 float qtz cut, float N

669 " " , Sericite.

670 Quartz qtz with S'ide work Weathered Rock at bend also.

671 float qtz cut. Trend to E about 15° edge of Boundary, ~~Sericite~~ to S.E.

672 Corner qtz cut rock at Corner Bdy weathered here to be certain.

673 float qtz cut W.R., float (W.

July 11, 1947

~~655~~

M.C. Rutile July 11, 1907

674 foot of cut
675 " " at Corner
676 " " brown W.
677 " " at Corner
678 " " Edge of Brown
679 foot of cut at corner, Coal and R.
680 " " " Symbole, Brown to W.
681 " " at Small, Brown S.
682 " " " angle small Retaining
wall and gum tree.
683 foot cut, at corner Brown S.
684 " " " " flat W.
685 top cut, into gully
686 at corner, by small, flat E.
687 on Symbole, foot cut, flat E.
688 small, flat S.
689 foot at Symbole, Corner Rock all along
690 " " Small, Corner Rock
691 flat to S., wooden Corner Rock
and brown here.
692 flat S.
P.M.
693. flat to W.
694 N.W. Corner of brown

M.C. Rutile

695 S. edge of Bottom, float 15
696 " " "
697 float to E.
698
699
700 " " " in hole between
cobble dump dist 8' N.
701 N.W. side of 5' pothole Basalt.
702 S. end of 4' x x Basalt mass.
703 N. end of Basalt.
704 float NEW.
705 " W. 8' N.
706 N.W. Comer Basalt.
707 N.E. " " " in the talus.
708 S.E. " " "
709 Top out float
710 Top & bottom dist, edge of road
15' wide.
711 W. edge road 15' wide.
712 E. edge of road.
713 S. " " "
714 N. " " " A Corner
715 N. " " road
716 E. " "
717
718
719 top of cut float
720

M. C. Rutile

July 16, 1947

721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741

M.C. Rutile July 15, 1915

742 Foot wall cut, N. edge round 9' N. on float. S to N on float.

743 Foot wall cut, edge of road 9' N.

744 " " " " , at Curve

745 White, weathered rock in cut beginning road 18' wide. On edge

746 at corner, rock gets green below, here and 745.

747

748 foot wall cut, road 9' E. in green rock 2' to wall, grade, 11' E. W. edge, foot cut, into float (begin 6' N.

749 Top & bottom of cut, in float. 9' to W. edge of road.

750 Top & bottom of cut, rock 12' W. float all around.

751 top cut 3' into road.

752 " " beginning of W. Q.

753 " " Earth Subsoil between 4' & Rock

754 " " Very sharp Granite outcrop. On edge of road.

755 Top of cut. bottom about 3' out along here.

756 at corner.

757 in angle of edge rock.

758 top of cut, Weathered Rock (also W.)

4 7 Shot from a opportunity all the so called prospects were worthless stamps.

M.C. Rutile July 15 1957

759 Comm 3 cm chrome Fork, float N.
760 on angle W & N. Top cut.
761 Sweet, fast & cut, top cut also.
762 In green weathered rocks,
broad rubble between
763 or coarse rubble between
764 & rubble. Green rocks
everywhere in broken up by
brown veinlets.
765 Sweet, fast cut, all float in
bottom of the Fork.
766 Sweet, float to South from here.
767 fast cut sweet pebble & sand.
768 Junction Fork & Fork N
769 fast cut. 3' from lowest W.F.
Sample
770 at Comm fast cut, float &
771 fast & cut, run to 770.
772 " " cut Sweet.
773 " " Green Rock.
774 edge of felsite dike, runs S.W.
Sample 72 from here.
This dike does not go to the
Top of the cut. It goes off
into some Swales & can be
seen Top. Photographed



M.C. Rutile July 15 1947

775	top out, above "Dike" this is all bowlt up here and with out moving in the westward.
776	Top out
777	Top out at South. the area seems to be in place and it has none of the breccia like appears in the west pit it all appears to be Basalt in any way Layers or decomposition.
778	top out, South wall on Basalt.
779	top out Basalt (Country)
780	Top out.
781	" "
782	" "
783	" "
784	" " in South angle
785	foot out, W bank. Each Bank to N.
786	foot out, float N.
787	" " " "
788	" " " W
789	" " " "
790	" " " "

M.C. Rutile July 1947

791 foot cut, float w.
792 " "
793. E. edge of float
794 at road intersection. N. side.
795 S. Road, S. side float
796 N. edge Road. This is on fill bank. Last 2 wells mapped only at edges
797. edge Road (N) 9' wide
798 Corner of new Road Branch.
799 corner boundary (outlier)
800 End Road Test.
801 foot cut. Narrow elevated block here. May be only rutile bearing or residual deposit.
802 foot of cut, in old float gravel
803 " " " small.
804 in creek, float
805 at Corner.
806 foot cut.
807 " in corner,
808 " sharp small.
809 Top cut. S'ly corner of Small cut.
810 top cut.



M.C. Ruffle July 1947

811	Top & cut, to angle, flat	
	to N.	
812	Small top cut	
813	Top cut middle below	
814	5' to come from here	
815	Top & fill. 15' wide	
	at top and bottom on E.	
	side	
816	S. side & fill 15' wide at top	
817	S.W. corner & fill top.	
	Most fill to South. Top to	
	about 17' wide here	
818	top fill. bottom 7' South	
819	" " 5'5.	
820	" " and bottom	
821	foot & fill.	
822	" "	
823	Corner & fill. at foot	
824	" " at foot.	
825	S. corner & fill top about 15' wide	
826	top fill bottom " 7' S.	
827	top & bottom " fill	
828	" " " fill.	
829	E. edge road 10' wide	
830	W. " "	
831	E. " "	

M. C. Rutile 61. July 15 1947

B32	S.W. Corner of building.
B33	S.E. " "
B34	N.E. " "
B35	foot of fill, and 15' W.
B36	" " cut face and 6' N.
	Int 8'
B37	W. edge, road C. 9' W. C.
	Tailings and flat 6' W. End road
	Int 30' E.
B38	Tailings to west, flat E.
B39	S. side of tailings dam.
B40	E. " " "
B41	" " " "
B42	Top of fill embankment, 6' back
	to bottom.
B43	on flat, tipping marked
	on ~~wood~~ post. Edge tailings N
	On tailings, road 10' E S
B44	On tailings, 20' W & Creek.
B45	In Creek bottom. Edge
	of tailings.
B46	In Creek. edge of tailings
B47	At bend in Creek.
B48	in creek bed, flat E
B49	" " "

M.C. Rutile July 15, 1947

850 at angle in Creek to W. Calcy's E flat E, flat W.

851 at angle, flat E & W.

852 Centre Creek, flat E & W.

853 top of cut on Bench (?)

854

855 top of cut at comp.

856 " " " " "

857 top of cut, white weathered Rock.

858 " " , Hop Comp.

859 " " , irregular to here.

860 top cut.

861 " " at Comp. goes in 6 where 2 left off before.

862 top cut, bottom 7' E.

863 " " , Small on Creek and Brown Rock.

864 flat 2 cut green weathered rock.

865 " 2 cut " " "

866 flat " "

867 Comp top of cut. Broad Terrace plan

868 top of cut at comp. on Bench

869 " " cut on Grey Weathered Rock

870 Top " "

871 " " " Rock bottom E.

M.C. Rutile — July 16, 1957 — Tuesday

B72 — Top ¾ cut in angle with through line.

B73 — Top ¾ cut at Corner

B74 — Corner, Top ¾ cut.

B75 — Left, 16 Photomicrography

B76 — Top ¾ cut, bevel, at Corner.

B77 — " " ¾ at Corner.

B78 — " " at beginning, Dirt in bottom of the cut.

B79 — Top cut, mark at corner all the way Heeled left.

B80 — Top cut, Part 5 through line

B81 — and bottom cut. Part 5 and 6

B82 — Top cut. Top is 10' wide at this point. Bottom is 6' at

B83 — Top cut at end.

B84 — " " at corner.

B85 — Part ¾ cut in angle, heavily mottled white color.

So called "flute" is running through one of what looks like veins, all very rotten



M.C. Rutile July 16, 1957

886 foot at triangle. Contact here between sweathered grey basalt and the reds and whites, sweathered rock. Float N

887 foot 2 cut, float E.

888 " " " Bonanza Basalt unit E.S.

889. End of basalt here. Map on map from foot point. Float N.

890 foot 2 cut, float E.

891 " " " Sweathered

892 " " " of Dike - Apex of Vertical dike 25 ft. wide Sample #73. 8' S to 12' Sweathered Green sweathered dike. Very Dark Dike Rock is about 60° N. Two sweathered to get Comp. b.

893 foot 2 entering dike

894 Dense basalt, float out

895 foot outside dike rock #892

896 " cut. Comp. sweathered

897 3' S to edge 2 inch dike. Same as at 894 Sample #4 on dike

M. C. Rutile July 5 1957

898 fort ½ mi.

899 See Sketch comm, typical yellow
mechanized material.

900 Dec 5 E ext, float as

901 fort ½ ext, begin with the O Rock

902 " " " in all

903 Comm, brown, ext N 5 ext.

904 In outcrop, same below, fort
ext, float E.

905 in outcrop, E ext.

PHOTOGRAPH June 7
Abbitt and Gandt contact.
at Brown Comm

906 at Comm. Weathered grey rock
yellow mineralized below.

907 Without white rock begins at
906 into hill, small Veinlets

908 In angle fort ½ ext.

909 fort ½ ext at Comm

910 " " " In Soil.
E. there are many float
some always gritty. all in
soil and trace on trail.

911 yellow Ext N. flat S.

M.C. Rutile July 1927

912 yellow sand (Copper-bearing-Cuprite)
& N.

913 Coming yellow Rock

914 Small, foot 3 cut.
Crust formed for glass water
Thin only 4 ft pit (cable note
to E.) has cable wheel on
both mallet Basket on a
green wooden and probably
knot. The one near the
yellow rock only 10 inches
in the bottom of pit.

915 Brown sandstone rock. Small
foot 3 cut Green. (on Bed)

916 " 3 cut. Defunct Basket
keeping this.

917 at Comm Basket.

918 foot and keeping on.

919 " " top - 1.

920 Top and foot 3 cut

921 On hill N. Top cut. Small Rock.

922 top cut

923 top cut. Small.

924 foot 3 cut big small at Basket



M.C. Rutile July 16, 1947

925 top cut.
926 " "
927 " " 20' NE fault cut
928 " " at corner
929 Top cut.
930 " ", fault cut.
931 fault cut. Wallace Creek, R.
932 " " ", Thin coal corner.
933 Top & cut.
934 " " ", at corner.
935 Top & cut exposing dark lustrous coal.
936 " " "
937 " " "
938 " " " entire chute showing top.
939 " " " " " " "
940 Top cut, E. side of fault.
941 Top & cut at small angle.
942 " " " "
943 " " " "
944 " "
945 " "
946 " "
947 " "
948 " " Showy pyrite

M.C. Rutile

949	Top E. [illegible] cut.
950	" " cut
951	angle cut
952	" "
953	Top cut
954	"
955	Top Shoulder cut
956	fast cut. Within Boundary to here. Fresh dipping line
957	dark. igneous rock 2" dike here. Dips E.
958	Completely weathered black dike
959	fast cut
960	" " Dike
961	E dip 10° with road
962	" " "
963	Center of Creek.
964	July 17 1917
	↘
965	S.E dipping rock
966	N.E. "
967	N dip 4 and 10 Degrees
968	" "
969	S "
970	N "
971	S "

M. C. Rutile

July 17 1967

972	N. edge ground.	
973	S	
974	N	
975	S	
976		of Corn. Island
977	E edge ground	
978		

M.C. Rutile. July 17

A

A1. Rutile veinlets run roughly E-W. Cyanite is incorporated through out the material. 77A from here. The Basalt block has been veined and altered by the mineralization. Jewel 18A is of altered Basalt

A2 These points are all
A3 Stakes in the small area
A4 mapped on 10 scale.
A5
A6
A7
A8
A9
A10
A11
A12
A13
A14
A15
A16
A17
A18
A19

There Numbers will be on the first ground area. Jobs 1-4 Brecciation area from 1 2 to 4 the Basalt to wet prospect is a North east direction and fault trace to the pitted mesa area

M. C. Rutile

6A Here basalt is altered by
veinlets to a bluish mineral

A 20

A 21 Special area Points

A 22

A 23

A 24

A 25

A 26

A 27

~~28~~

~~29~~

Hardy Property July 24 & 25, 1947

Now on Hardy Property. Numbers will be "H" numbers.

H1 There are Traverse Stations

2

3

4

5

6

7

8

9

10

11

H12 Top of dump at W. end of pit.

13 Stake - 0

14 N. end of pit 3' wide (no cut, pit is in red clay with a few rock rock fragments.
(Note in one pit determine the type of rock and shape.)

15 S. end of pit, 3' wide. 3' deep at this end.

16. N. end of pit. 8' deep at this end. (Pit in end)

17 S. end of pit. 3' deep.
about same depth all along.

Hardy Property July 25, 1957

H 18. E end of pit, 9' deep.

19 W. end " " 9' deep. much more fragmental material at this end.

20 E. end Shallow trench 2' deep. in red clay.

21. W. end of pit. more abundant fragments.

22. E end 3' deep. In solid Norcanite. no more float at the surface here than anywhere else in the pit area either. Sample H1 from here.

23 W. end of pit. 3' deep all Norcanite.

24 Similar. edge of completely frozen covered ground.

25 Dark float to W.

*26. W. end of trench 10' deep. in red clay. Good place for Sample.

27 E. end of trench 8' deep.

28. Edge of rock float. E. end of 3' deep trench. abundant fragments but still red clay.

29 W. end of trench. 6' deep.

30 Heavy rock float

31

Note all pits (trenches) are roughly 8' wide and 8 yards are taken in counts of each 8.

#26. The bottom of the pit is a yellow soft clay like material unlike the material in the surface red clay. In the bottom of the pit the rock is almost entirely fragments and fragments of mineralized rock. Sample #4 is from here.

Haldy Property July 25, 1947

H 32 W. end of pit 3' deep in red clay
33 E. " " " 9' deep
34 Nothing, not even Hemy Flat.
Trench put up in here. Hemy flat 40°S
35 Hemy flat to N.
36 At Sharp corner Hemy flat.
37 W. end of 4' deep Trench. 6-8 Hemy flat. Pit in clay
38 E end of 4' deep trench.
39 Hemy rock flat, Small
40 S end of trench 3' deep. Fossil clay fragments not abundant.
*41 W. end of trench. Too deep to become with rod. Get Sample here (15') probably deepest in a topographic low for a good sample
42 W. end 6' deep trench. In red clay.
43 E. end of 3' deep pit.
*44 W. end of 3' pit
45 E end pit.
*46. W. end of pit. 4' deep. red 2' below surface, clay to N



At 044 we have a bed of red clay dipping about 5° S. which is passing through Solid Monzonite. Get a sample of red stuff here. also of Monzonite. PHOTOGRAPH ALSO.

Sample H-6 is from bottom of this trench.

#46 This is the highest point on the property.

The contact is much less weathered and has a rock fragments on fresh Syenite. Contact is in clay. Strike of contact is N 60° W. Dip 60° NE. Monzonite is not abundant (is even present below the Soil test. Pit is 5' deep in "Dark" Sample H-7

Haldy Property July 25, 1947.

46 47	E end of 9' deep trench. No clay at this end
48	W end of 4' deep pit, in clay. edge of clay
49	E. end of pit.
50	S.W. Corner 3' wide trench. No bedrock. Nowhere over 3' deep. Nowhere first to E.
51	W. edge of trench at angle 4' deep. Mainly red clay.
52	W. end of trench, 9' deep, W. clay.
53	Nowhere first E.
54	S. end of trench 8' deep, in red clay.
55	N. " " " 5' deep.
56	S end of trench 14' deep, in clay.
57	W. edge of trench 3½' deep.
58	NE corner of pit 9' deep
59	E end of 3' deep trench.
60	W. " " 9' " " in red clay.
61	E end of 5' deep trench.
62	W. " " 4' " " in clay.
63	E end trench. 3' deep. No bedrock to 5' W. in red clay.

Hardy Property July 25, 1927

64 W. end of trench 2½' deep in marly red clay. about 10' W to Heavy Novaculite float.

65 Heavy Novaculite float 6' W.

P.M. 66 SW corner of trench. 3 days. 3' deep.

67. Comm. pit. clay with lots of float which was moved down on to it.

68 at Comm. W. side of trench.

69. E. side of trench. In Novaculite to E. and 10' W.

70 N edge of cut 3' wide runs 8' E into solid Novaculite.

71 E. edge of trench. Red clay but with a lot of fragments mixed in.

72. In side corner of trench. Swell to last point.
Last Trench in from 3-3½ feet deep

73 N. side of Trench. 8' deep here.

74 S. end of Trench. Red clay 5' float.

75 N. in ½ side of another. 4' deep clay.

76 E. end of Trench. 10' W to Novaculite contact. This is a very sharp contact

Hoidy Property July 25, 1947

H 77 S.E. corner 3' inside Tunnel

78 S. Side of pit. red clays

79 " " " this is only 2-3' clays and pit barely gets through the purple float. Clay through

Δ80 Station

H 81 E end of bench 3' clays, red clay.

82 W end of bench 2' "

* 83 " " " " 2' this bench is all in Navajo. about 4% iron near Δ80

84 E. end of pit 3' clays. Clay checked 4% and green material. Can see none in place

85 S. Side of bench 3' clays, some 12" in Navajo.

* 86 N. edge bench 5' clays. Face 8' E. Dike at entry (1 ft) into Navajo. Face 15' to Navajo. Clay material here. Get sample here.

87 (Shot from Δ6) N. end of bench 2' clays In Navajo. Sample H13

Not visible in any of the pit but must be Contact line which appears on float on the surface. This must have been a dike. That part of mountain.

#78. This material is a capped over rock fragments and Comes in contact with clay in dry Sample H9 is typical.

#83. 4% iron shows parallel to pit but is altered Navajo.

Handy Property July 25, 1947

H 88 S.E. Corner of pit. 2' deep.

89 } Compact aligments of 2' deep pit, no.
90 } floor.

91 Center of pit about 5' wide

92 E. edge of pit, about NE Corner of Shaft. 12 to water level in Shaft

93 S.E. Corner of shaft.

94 ~~S~~ S.E. corner of 3' wide deep to E.

95 N.W. Corner of shaft. water in Shaft was 3' deep.
Sample H-2 was of "Clay" in this Pit.

96. S.W. Corner of pit. appears to have gone underground a little way.

about Normal

95. 6'

Solid Novaculite } ½ Clay } Nonmalite

W side of pit.

E. side of pit in solid Novaculite.

best developed in Pits 91 and abundant also O3 and O Smoky O3. all in run through by Fe OX Corona and Veins. No Sulphide staining.

Hardy Property July 26, 1947

97	N. side ground at bend.
98	" " " " 7' wide
99	" " " "
	DZ is in middle of road.
100	N. edge ground Curve between.
101	S. edge of road.
102	N. " " "
103	" " "
	DZ is in center of road at bend.
104	N. edge. Begin smooth curve to here
105	N. " Straight to here, then begin to Curve.
106	S. edge of road.
107	" " " W. edge 7 to 8' wide. Side. it runs ⊥ to road.
	DZ is in center of road. Straight from last point.
108	N. edge ground.
109	" " " curving from last point.
110	" " "
111	N. " " intersection ground.

July 29, 1947

Christy Property

C-1	First Station
C-2	Second Station
C-3	NW Corner Pit A-1
C-4	NW Corner Pit A-2
C-5	NW Corner Pit C-1
C-6	NW Corner Pit C-2
C-7	NW Corner Pit C-3
C-8	NW Corner Pit C-4
C-9	NW Corner Pit C-5
C-10	SE Corner Christy Garage
C-11	NW Corner Pit D-1
C-12	NW Corner Pit D-2
C-13	NW Corner Pit D-3
C-14	NW Corner Pit D-4
C-15	NW Corner Pit D-5
C-16	Third Station
C-17	NW Corner Pit A-3
C-18	NW Corner Pit A-4
C-19	NW Corner Pit A-5
C-20	NW Cor Pit B-1
C-21	NW Cor Pit B-2
C-22	NW Cor Pit B-3
C-23	NW Cor Pit B-4



Christy Property

July 29, 1947
Christy Property

C-24	NW Cor Pit B-5
C-25	NW Cor Pit B-6
C-26	Center of Road - Elevation Shot
C-27	NW Corner Christy House
C-28	NW Corner Pit E-1
C-29	NW Corner Pit E-2
C-30	NW Corner Pit E-3
C-31	NW Corner Pit E-4
C-32	NW Corner Pit E-5
C-33	S end of N-S trench
C-34	Test Pit in trench at C-33
C-35	N end of C-33 Trench
C-36	NW Corner Pit F-1
C-37	NW Corner Pit F-2
C-38	NW Corner Pit F-3
C-39	NW Corner Pit F-4
C-40	E side of road
C-41	W side of road
C-42	E Side of road
C-43	E Side of road
C-44	W Side of road
C-45	Fourth Station

Average width of road = 11 feet

Sketch of Christy House & Garage



4' W of W side of rd.

Christy Property

July 29, 1947

Christy Property

Pit notes.

A1 6' z clay and rock fragments (903-947)
resting on Novaculite.
No concentration of fragments
toward the solid rock. The
material seems to be just
resting on the novaculite. The
novaculite surface is sloping
gently to the south 10°-15°.

The novaculite is the hard
flinty variety not at all friable

Sample ~~C~~ is from pit.—
~~Novaculite sample.~~
C-1 is solid novaculite clay.
Pit A1 is 13' deep.

A2 6' deep.
NE side of pit - gossan
fragments in clay
C-2 is sample of above
In southeast corner 3 ft of
red clay - underlain by
1 ft of pure clay underlain
by gossan material in clay
C-3 is sample of pure clay

Pit A1

The top of novaculite is covered clay
veins of white clay in novaculite
probably in fractures

Dip west well veins in novaculite
dips 25° to south - 4 ft up to
is clay with heavy iron oxide
on surface

Sample C-6 is vein material
Novaculite is chalky - gray tan
tripoli and is white.

Christy Property

A-2 Pit

A-2 Grd-
C-4 is sample of green material -
Gossan material has dip of about 30° to the south
Bluish Novaculite on dump
Bottom is slumped clay at most
Gossan material gets more solid toward footwall
C-6 is most solid of gossan material

A-3 Six inch vein of white clay interspersed in gossan
Pit is 9 feet deep
Blue gray novaculite on dump -
One clay vein in gossan dipped 30° to the south
Clay veins are variable in thickness

A-4 Depth 11 ft
One vertical clay vein
Mixture of clay & gossan
No Novaculite on Dump



Christy Property

Pit A-5 — 6 ft Average depth
No Novaculite on Dump

B-6 — 4 ft deep Crud

B-5 — 15 ft deep Crud

B-4 — 11 ft deep Crud

B-3 — 8½ ft Crud Black Novac. on dump

B-2 — 4 ft deep Crud in Novaculite on dump

B-1 — 4 ft deep in Novaculite

C-1 — 16½ ft deep in Crud

Christy Property

Pit C-2	14 ft Deep Abundant Clay
C-3	15 ft Deep White Clay Seams + Crud
C-4	13 ft. Deep Crud
C-5	14 ft Deep Crud
D-1	14 ft Deep Crud
D-2	12 ft Deep Crud
D-3	27 ft Deep Crud
D-4	12 ft Deep Crud
D-5	13 ft Deep Crud

C1 Christy Property

Pit E-1

4.5 ft to Novac. in NW
Corner of Pit
7.5 ft to Novac in SW
corner of pit
Dip 40° S } Novaculite
Strike S 75 E }
Novaculite shattered and
Bluecubite in color
Total Depth 15'

Pit E-2

Seven feet deep

Pit E-3 14 ft deep / Gook

Pit E-4 12½ ft. deep Gook

Pit E-5 12 ft deep - Gook

Trench betw. E + F pits
3 ft. deep

Christy Property

Pit F-4	9 ft Deep	Gunk
F-3	9 ft Deep	Gunk
F-2	11 ft Deep	Gunk
F-1	12 ft Deep	Gunk

Need water to pump

Christy Property

C-46 Fifth Station

C-47 SW Corner Sec 16 4 ft West.

C-48 Wedge of road 3. edge of

C-49 SW Corner of test pit - Pit is

C-50 So. End of trench 4' deep

C-51 NW End of above trench

C-52 N End of NS Trench

C-53 S End of above Trench

C-54 SW corner of excavation above tunnel - exposed Str. N25E Dip 50° S

C-55 Station 6 1 ft W of trench

C-56 Cen. E end of "L" shaped trench 4' deep 4' wide

C-57 N end of "L" shaped trench

C-58 Center and S. end of above trench

C-59 Center of caved shaft 4' x 5'
Sample C-3 taken from dump

C-60 Center S. end of trench 3' wide 3' deep

of edge of road
hornblende - 8 ft of quartz above it
located at bottom of excavation
7 ft. deep 13' in diam
→ 4 ft wide
→ 2 to 4' deep 4' wide

Thin-bedded Hornblende - with
wallpapered in places

Christy Property

C-54 to Mouth of Tunnel N-17W
Div of elev betw
Floor of Tunnel at
Portal and C-54 = 30.5'
C-54 is above portal
Tunnel bears S 32° E at portal

C-54 - Portal Slope Distance 39
Slope ∠ - 30°
39 x .5 = 19.5
Sample # C-7 from portal of
tunnel probably Hot Springs S.S.

C-61 E end of square trench
2½ ft deep 4' Square

C-62 Station 2 - 1' South of road

C-63 E-W Trench 3' x 7'
Sugary Novaculite on Dump

C-64 N end of N-S trench
Sugary white Novaculite on
dump - Pit 4' x 7'

3' 5.5 = 12.5
+ 2.0
+ 12.0
30.5

.577
39
5196
1731
23.506

Christy Property

C-65 NE end of rectangular 4'x8' trench 3 ft deep massive sugary white marble on bottom Sugary Novaculite with white quartz veins on dump

C-66 E side of N-S Road at bottom of hill → E

C-67 N. side of road

C-68 Station 8 - 11' N. of Medge stake.

C-69 S. side of road

C-70 N. side of road on contact of Old ? Blue gray sugary Novac.

C-71 Center of road at high point

C-72 N side of road sugary white novaculite



Christy Property

C-73 Sugary white Nepheline Massive Boulders on side of ravine probably in place

C-74 Massive Syenite outcrop in steep bank of Chamberlain Creek ravine

C-75 Massive Syenite in colect 8' North of road Sample #

C-76 Massive syenite on slope of Chamberlain Creek ravine

C-77 We dug a trench 5½' deep by 6' the North end of the pit was in "Syenite" fragments from about 2½' down. The remainder of the pit was in clay

C-77 Whether we got the "Salt" purple or not is a question the syenite fragments were about in the North end of the pit and not in the rock and a lot were from the clay near the contact I am inclined to say perhaps that we only a fragment of the purple may have been Syenite. The Syenite is the same as at the Hardy Property.

U.C.R. Bet.

Aug 9, 1946

Wall Geology of Det.

West of D 270 and D 199 the pit walls are in ore. The soil is 2-3' thick with no evidence of a gravel bed. Pressure excavation to the north would strip the ore for a few feet.

D 183 Creep to North this might have stripped as much as 10 feet. There is abundant wash from gravel without rock. The floor of the pit is a soft brown weathered rock, probably dyke rock. The material is mottled in color and of varying hardness. No definite decision.

Island mantled residual soil may be weathered "protore". Sample 78 10' W of D 352 is this material. The weathered rock is cut by numerous weathered veins, even by the yellow mineralized rock.

West of Δ 352 — Here there is evidence of alteration zones found by veins cutting the "Peridotite. West of the veins the rock is green in color and harder, with abundant pyrite. 2' from the vein (the yellow Mineralized section) the igneous rock is dark green and very fine. Sample 99 is from the contact zone.

Δ 593 Even, walled rock. Sample 100 from here. There are numerous veins within 100' of this. Like rock of "Peridotite". The vein is 2 feet from the Δ.

Δ 590. Even walled rock. Sample 101 from here.

4. 11.

Hard rock 1' zone
X 99

Soft weathered

Aug. 9 1927

Δ 358. E ~~[illegible]~~ from the well rock is blocked to white or very light green. 27 is cut by a large concentration of veinlets. This zone general zone goes E to Δ 535. The stock just south is the usual green weathered rocks.

Sample 102 is at Δ 359

Sample 103 is at Δ 364

Δ 584 Contact of blocked and green rocks. The contact is dong a vein and is quite sharp.

104 is the blocked Rock

105 is Greenrock. The stock just to the south is the same blocked Rocked

Δ 576. from here E to the first gravel bar on top of the rock.

Δ 571 Sand and gravel are about 8' deep. This goes to the end of pit E.

W. 576 E

Rock | sand | gravel | 6'

Aug. 9, 1947

△ 518, go from grun to bleached rock East ward Sample 106 is bleached rock

△ 507 fork point, rock, well as a grun rock with numerous veins. Sample 107 for this Date

△ 488 Green weathered Rock. all along line. Sample 108

△ 483, grun weathered rock along this road to △ 506 veins are not shown.

△ 671 fine fresh. doesn't weathering to a dark green rock. Sample 110 from here 111 to 112 is weathered rock.

Aug 9, 1957

East Pit.

D 890 from here West the wall shows area 7 feet, rock like base of Dayton 118 w/ green weathered rock. The Bentonite appears to be the country Rock in place. This is true for the wall from D 772 D to 886. This area has abundant basalt fragments in ~~the~~ ~~sed~~ ~~ments~~ in weathered green rock to show its true character.

Some for 771-731 along that wall. Sample D 113, D 902 here the wall looks like weathered pumbite. The gravel colluct may run to W. of 893, and E of 897. Sample 114 from here.

Aug. 13, 1947

980	A	on traverse
981	"	
982	"	
983	"	
984	"	
985	"	Churn drill hole (auxiliary hole)
986	"	
987	"	
988	"	
989	"	
990	"	
991	"	
992	"	
993	"	
994	"	
995	"	
996	Sand, mud, red clay	
	Sample #6 in 6" bucket	
	Surface.	
997	Shaft about 5 miles S. of Bonita	
998	Very hard, mud. Sample #7 in	
	bucket. Sand lying in 10' N	
	West is sample #8	
999	Shaft mud, light	

Note traverse closed on line.

Aug 15, 1927 Cloud.

1030 Swell, at contact with Base of fourth

XI Swell, on Equator

2 Swell, south edge of Bank. appear Clay Earth.

3 N edge of at, South edge Bank.

4 " " " " Clay.

5 E. ends cut. 12-15 wide.
this is cut. cut is in clay

6 Straight on Clay

7 Swell, clay on E. many Pigmies
Plant

8 On clay, Swell

9 On Bank

10 Station, flatter up here.

11 Fishing out slightly better
Larger Swell. Nothing but
plant.

12 Out crop Pearly, Limestone
porphyry. Feldspar phenocrysts
3" to contact & Clay by. Shock
rock. Can this be an inclusion
Blue Rock Pigmies.

13 Cross a Veg. Blue rock - Mouth
widening at least 45° E
By a Swale Swell Rock

Aug 13, 1942

X-14 S edge - basalt float
below.

15 Faint outcrop, No outcrop.
float is Syenite

16 Light basalt Dark. Dirty
black dark basalt. outcrop.
Contact with Syenite in 15'E.

17 On Syenite in basalt outcrop

18 On Syenite

19 Slight float is Syenite.

20 Dark gray porphyritic rock in
place.

21 about same as 6 adjacent
(low mtl. to west)
float).

22 about same as 6 adjacent
E W.

23 N side - basalt.

24 Syenite outcrop.

25 Syenite

26 most is basalt Syenite in
soil (float) begins to be the pre-

27 Syenite.

28 Syenite outcropping

29 Basalt & N [illegible]

Sedimentary at 20 & 21 & 22
might have been altered Syenite was
a very fine [illegible] Syenite Porphyry
Now likely it was dacite-Porphyry
vein like in Tar with 7 pit.

Aug 14, 1907 Thursday

X 30 Gentle Slope, Severely Shattered
on Exp 2 Clay Egress

31 on clay and S. many pieces.

32 On Shot

33 Rib & Level ft. Clay between
places, Small Vein.

A 98# on right of Exp, Shot.

34 Exposed on Surface, Shot E S

35

36 Shot Fairly Straight, Shot

37 Shot

38 Shot. Seem through two
Shots on Right, not Exposed.

39 Exp not

40 Shot, about 3" [illegible] Exposed

41 Shot on Shot [illegible]

42 Fairly Shot.

43 Slight [illegible]

44 Shot Exp [illegible]

45 Exposed Shot, Clay [illegible]
possibly

46 Clay

47 Exp 4" Clay Shot.

20 + Shot Exp. Shot Exp on
Exp 10

Exp Shot to [illegible] Exp [illegible]

July 14, 1947

48 Small Syenite float.
49 Small Syenite and esp
50 med Syenite.
51 med Syenite.
52 Small Syenite and esp
53 On DC clay, Syenite 12' South
of 986
54 Small red clay.
55 N. edge 15' wide but in
eroded ravine Lt. Brn Bet walls
56 Small Syenite float Esp
Dec 15, 1947
57
58 On
59 Chum. Small lake
60 N. edge of T. 12 with red
clay; not known if good yet.
about 3' clay over
61 Float Chum
Secured
62 Float, red clay.
63 clay, Small
64 outcrop NE Sec 20 small
pod in
65 Small Dist red clay
66 Straggly float

Aug. 15, 1967

X67 Float only one day.

69 Very strong riparian flora.

69 Riparian flora

70 In center of Creek.

Sample 121 & 122, grab 7 ep.

[illegible]

71 Bank is still [illegible]

72 Center Creek, no [illegible]

73 Entering Creek [illegible]

[illegible] 44

meadow. [illegible]

are in float

74 In left center material. [illegible] Board [illegible] Sample 123 [illegible]

75. In Center Creek to S. Creek to the left is still [illegible]

77 Grid Unit 35

Sample 124

Sample 123

gravel

Aug 15 1947

X 76	Cuts of Creek [illegible]
X 77	" " flint, gravel.
X 78	Limestone. clay. flint.
X 79	Sandy flint
X 80	flint
X 81	Dyenite and coppery.
	Pebbles in flint, 50 Cuts
	Obsidian.
X 82	Dyenite and coppery. with silt
X 83	Dyenite " Sandstone.
X 84	Rocks like Chert Flint, Rock, flint
	in Dyenite
X 85	Heavy dyenite flint
X 86	Sweet flint 50 Cuts 20
X 87	A
X 88	Sweet Dyenite
X 89	Dyenite, sandstone
90	Dyenite
91	about Dyenite & clay flint.
92	clay 6
93	penny Dyenite flint 50 silt
94	Flint, Cuts, clay etc
95	Flint & stones.
96	Flint clay stones Cuts & Tools 72
97	Cuts & tools & flint

Aug 15, 1947

~~X96 Gully & Creek, at head~~

X98 Swell, on 400 contour

X ~~100~~ 99 Swell, Switch between

X 100 on center & Sweetwater Gulley

X 101 at head of Sweetwater Gulley. 3' op.

X 102 " " " " " , good ~~4~~ 5' ban

This gulley cut in red clay, with

rounded Tgravel bottom. The

clay appears to be the resulting product

X 103 Red clay, flat to

X 104 Low knoll, red clay

105 Red flat.

106 Gully cut into clay.

107 Flat (Sylvan) Base 6 ft.

108 Clay Tgravel flat.

109 Tgravel

110 Clay Tgravel flat.

Bottom material is common

along this slope.

West side of swamp limits and this

general dir of flat.

111 Red clay Tgravel flat.

X 112 " " Small gully flat.

113 Red clay - washed rock

114 Small Red clay

Aug 15 1947 Afternoon

X 191 Small Gully, 10' undercut.

192 N side creek, gully cut 7' wide

193 Creek bed.

194 Low knoll, some clay with rock

mixed with surface. Thin soil, surface

X 397 covered to 4' below.

195 Small Gully, cut from 15' to 10' th

196 Gully & Creek, flat bed.

197 Gully & Creek.

198 Small Gully Cut.

Aug 15, 1907

X 115 Sandy, Red clay.
X 116 Red clay.
X 117 Red clay,
X 118
X 119 Red clay.
X 120 foot of cut, ... of cut.
X 121 " " " cut Common
sandy material with bed ...
X 122 foot of cut
X 123 Top of mound. Bottom ... 15' NE
Aug 16, 1907
X 124 Chert drill hole. Rock ... Depth.
Started in Mound #2
125 Sandy red soil.
126 In mound. Out cut. (Top)
127 Depth of dig to Gravel ...
128 This is L.S. Hole is 2.8' deep.
Struck at bottom.
129 Chert drill hole.
130 W. Edge of dump.
131 Top of cut, dump to ... Bottom
of cut is 1' E. ... foot.
132 W. edge of dump.
133 Top foot.
134 N.W. ... cut.
135 Top ... cut
136

Aug 18, 1907, Monday
X 170 Type-sheet. Soil.
X 171 Chert drill hole.
X 172 Sheet-wash soil
X 173 "
X 174 "
X 175 "
X 176 "
X 177 On soil, flat. In deep ravine.
X 178 " " " 20' E ravine.
X 179 In Ravine ... cut.
X 180 " "
X 181 " "
X 182 ... Creek 1/2 E. 40' South to ...
Mark and Collect
X 183 From a Mound cut ...
X 184 Deep ... cut ...
185 Soil
186 Low ... Sandy, ... flat.
Flat ... flat ...
187 Sandy, red soil
188 Sandy ... flat
189 ... 12 ... 20'
190 foot of ... ravine.

Aug 15, 1957

137 Top out, bed 15' [illegible]

138 E edge of dump

139 " " "

140 " " "

August 16, 1957 Windy

142 [illegible] Top about, soil.

143 Slight rise 25' east.

Dw Track.

144 Top - [illegible] soil.

145 [illegible] to bottom of dump

end Edge of Track.

146 [illegible] end of

[illegible] Knoll about end

[illegible] Creek. Creek

20° E

147 E edge dump

148 W. edge gulch, [illegible]

149 E. edge gulch, Start pit

No [illegible] pits.

150 Begin E. [illegible] pits.

E pits [illegible]

154 E edge of pits [illegible]

152 " " "

153 " " Soil about

four feet [illegible]

pits.

E. & S. [illegible] Open pit and the

[illegible]

x154 [illegible]

x155 [illegible]

[illegible]

x156 [illegible]

x157 [illegible]

[illegible]

x158 [illegible]

[illegible]

x159 E edge [illegible]

x160 E [illegible]

x161 [illegible]

[illegible]

x162 [illegible]

x163 [illegible]

[illegible]

x164 [illegible]

[illegible]

x165 [illegible]

[illegible]

x166 [illegible]

x167 [illegible]

x168 [illegible]

x169 [illegible]

See previous page for continuation

M.C.R. Sample Notes

116 at Δ 996, Red clay Soil Sample 6" deep. TiO_2 found. Check ilmenite.

117 at Δ 995, Soil Sample over mafic content.

118 at Δ 998+10' N. Syenite in place - Thin section.

119 at Δ 981, Syenite rock.

120 at Δ 971 altered Shale(?) fault remnants in yellow clayey soil material.

121 at Δ 969+20', Syenite

122 In direction of Syenite at Sample place at 121. The Syenite appears to have the chilled contact.

123 at Δ X74 Sample of Basalt in Creek bed.

124 Ca shale for ΔX75.

M C.R. Pit Sample Nos.

106 at D 518, Weathered rock for heavy mineral.

107 at D 507 for thin-section.

108 at D 489, Green weathered Rock for Heavy Minerals.

109 at D 493 Green weathered rock for heavy minerals

110 at 671 Fresh rock for thin-section

111 W of 671, green weathered rock for heavy minerals

112 "Basalt" from wall at D 890. Here the sample is from a fairly fresh remnant surrounded by weathered rock. (got thin section)

113 Green weathered rock for heavy minerals at D 902.

114 at D 901, weathered Rock for heavy mineral analysis.

115 D 906 Sample of "Sandstone" (thin section) This is a remnant from well weathered material.

Sample	Numbers and Notes
98.	M.C.R. Pit, Sample from Platform Isolated resistant vein. For Heavy mineral work. From 10' wy 352
99	Contact zone between yellow clay and Basalt 6". Near 98.
100	at Δ 593, Weathered wall rock for heavy mineral analyses. ~~to water~~
101	at Δ590 Some Green crumbly rock from Pit wall. For heavy Minerals.
102	at Δ 359 Bleached rock for heavy minerals.
103	at Δ 364 Weathered green Tuff ? for Heavy Minerals
104	Δ 585 Bleached Rock near contact. for Heavy mineral
105	Δ582 Cinder Rock for contact for Heavy Minerals

802 - C2
803 - C3 ← My Numbers.
804 - A92
805 - A94
806 - C6
↑ Chemist Numbers.

these are clay samples for TiO_2 analyses only.

9:30 Sunday M.
at Barlow Hotel.

XX Sample Rock at 0671 again.

Sample 8 Igneous rock below 0 8. also indicate on Map.

Sample Walls & pit and map colors. Accessory minerals may permit correlations.

Photographs

#1 Basalt mass on top of Gneiss. Bottom of pit at contact.

#2 "Felsite Dike"

#3 Side of Rock showing weathering. Probably same as "Felsite".

#4 Pit face showing Gneiss at bot of pit, then 4' of transported gravel. Fragments are felsite and gneiss.

#5 Photo of Kearney's Felsite dike w/ E. Pat.

#6 Alignment of Boroff to avoid green wall rock of pit.

Things to do.

1. Hardy Property.
   1. Go over pit at 4 46 agon
   2. " - - - 60
   3. Shoot Auger holes
   4. Look for N extensions.

2. Shoot Polaris at Big Pit.

3. Take Photographs.
4. See McKnight
   12 B Hickory St., Apt. 3
5. Shoot road corners at Big Pit.
   for orientation purposes, and
   Tie to Main Map.
6. Check the Geology under the
   island.

Mo-Ti Property Samples

~~M-1~~ Altered pyroxenite in footwall of vein

~~M-2~~ Feldspar-pyrite sample from M-38

M-3 Molybdenite sample from M-40

M-4 Fresh Pyroxenite Drill-section.

M-5 Porphyry dike in S.E. corner

M-6 Qz-pyrite material.

M-1 Vein material, fine grained feldspar-pyrite.

M-2 Fresh Pyroxenite

M-3 Porphyry dike. S.W. corner

M-4 Coarse grained feldspar pyrite material.

M-5 High grade Molyb. material.

M-6 Qz-pyrite material.

← What about the samples - One of fresh gneiss rock and the Qz samples?

M-7 Altered pyroxenite.

Drill hole sections for M-4 pg. 2 & 3

Christy Property

~~C-1~~	Nonmetallic sample Pit A1
C-1.	Solid material from clay Pit A1
C-2	Gossan fragments in clay from Pit A2
C-3	Clay sample from Pit A-2
C-4	Gossan material from A-2
C-5	Hadsit gossan material from A-2
C-6	Clay vein from pit A-1
C-7	Brookite-quartz from shaft dump
C-8	Hot Springs S.S.(3) samples from portal of tunnel on ravine on Chamberlain Creek
C-9	Massive syenite from Point C-75
C-10a	Clay from "Dug pit." dtd C77
C-10b	Fragments from " " dtd C77

Sample Note

Hardy Property Sample Notes

H10 Vein runs across trench (at 083) Central part of vein is FeO_x and Qz. Out wall is solid Qz (Coarse grained) Then Segregated Nonesite

Some Nonesite shows shiny regular surface with the ends of crystals. They appear to have been long narrow Vugs. Sample H12 is this sort.

H11 $FeOx$ & Qz from Center of vein.

H12 Nonesite with crystals 083

H13 087, Sample of wall rock may have been taken

H14 284 This is a weathered fragment in the clay for thin section.

VH-15 + Sample of wall rock of Nonesite out of pit at 286

VH-17 (H-16) Hot Springs 55. from N. side of Chamberlain Creek Syncline

Hardy Property Sample Note

Hardy Property Samples

✓H1	Specimen of altered Novaculite at Δ 22.
H2	Clay sampled in Pit at H 95
✓H3	Sample of dike in road, at Δ H 107 (dike: slaty shale)
H4A	Station 26; at bottom of pit (clay)
H4B	3 feet from bottom of pit Δ 26 (clay)
H4C	Iron stained clay as B. Looks like it might be something relating to clay
H4D	Rock fragment about 2' from bottom of pit (26)
H4E	Rock fragment from side of pit (26)
H5	Δ 41, clay from bottom of pit
H6	44 This is from the bottom zero pit in the "clay" vein in the Novaculite.
✓H7A	Δ 45; Rock fragment from half way up east side of pit
H7B	material around rock fragment
✓H8	Novaculite from contact with clay vein at 44A.
H9	Material from cut by trench near Δ 78

H3 discarded.

July 18, 1997

M.C. Rutile, Sample Notes in "A" area:

VA95 This is exposed vein in Basalt. The purple xtls. may be fluorite. (This is from a block of float F of A18

96 Photograph #3
This is the vein material in block, etc.

97 "Rutilite" Sample from North wall & very east extension of Pit.

July 13, 1907

A89 This is a sample of Dean-in Beulah.

A90 This is sample of Dean material - Salted away - clay and soft stuff to South

A91 Blue Clay - selected from general clay material. This is mainly for X Ray.

A92 This is the typical "Clay" material To me it looks like altered "Beulah.

A93 This is a sample of Dean material from the clay

A94 This is sample of clay material. This is called Grey Clay I have mapped.

Cable outcrops may be found in the "Grey clay" material it is most abundant in either the Yellow Rock or the Large Dean outcrop.

M. C. Rutile, Typical Area, Sample notes.

July 13 1950

A87 The upper portion of sample A87 is typical of all the other samples in this pit. The material is altered to a clay in spots probably due to weathering outside the remains of the material is hard and dense at A88(100') and the iron mineralization is starting on the rock appears fresh at the surface. Even the outside is fresh at that depth in spots.

The Rutile is in very thin streaks which do not extend for any distance. They do not have clear cut walls the rutile is quite coarse grained but not in veins.

Sample A87-1 is soft material.

✓ Sample A87-2 is hard material.

A88 1 day life in A87-1

M.C. Rutile, Special Area, Sample notes

July 13, 1957

The unit A86 is hard and white and shows abundant calcite. There were specimens of the gray clay material. The veins that are common were of both clay & the country.

A86-1 This is a fault gouge material & the material that makes

A86-1 Sample from contact of the yellow Hard material and a small basalt vein. This sample may be in all yellow but on the surface it is dark colored from the rest of the rock.

A86-2 This is a vein that shows the Basalt.

A86-3 This is about the purest of the kaolin it has 1/2 foot from A86-1

M.C. Rutile, Special Area
Sample Notes.

July 17

A81 ... In this altered Basalt along the edge of area to N. Do as this just more "Clay."

The yellow streak and the white area seem to be the same as the yellow, appears due to Fe Ox Stain. Cut away an area which under the Purpose would be different except for Oxide Streaks.

A82 Blue Clay sample Weathered basalt.

A83 Sample of area of this basalt. Shows why was selected as the basalt.

A84 Sample of Vein in Basalt. Vein is 6" wide. Appears altered basalt.

A85 Alteration of basalt caused by Veins. (Missing)

The

M.C. Rutile, Typical Area
Sample Data

Samples # July 17, 1947

M.C. Antile, General Samples.

70 at A 671, Dike (?) (Missing.)

71 Basalt (?) A 769

72 "Felsite" dike A 774 Stamped by Kinney

73 at A 892. Dark Dike.

74 ~~Dike at A 892~~ A 897 Dike (Hold)

75 Igneous rock at A 956 (Hold)

76 2" dike at A 957

— Special Area

77 at contact granite and Basalt with pink, reddish rock, has a lot of calcite. At the contact there are white veins at A 1

78 at A 1 sample of altered Basalt.

79 This is clay-like material. I do not think it is altered Basalt. It is typical of the light colored material. Clay at top and solid when deeply

80 In a typical white vein like in the clay like material. This vein is literally the Basalt. No effect can be seen on the clay-like material. (Missing)

← - These are for thin-sections

No sample # 69